


**Structural Evaluation Report  
for Existing Buildings at  
Livingston Mountain Communication  
Camas, Washington**



In conversations with the Clark County Building Department, there were mandatory requirements for upgrading the existing structure provided occupancy to a higher hazard

A brief calculation of wind loads was made per the current IBC Wind on the accessory garage building and was used for safety checks. For was determined that seismic forces govern design of the primary lateral further wind load analysis was done. Consideration of geotechnical was limited to the quick check procedures of ASCE-31

Existing buildings are evaluated to one of two performance levels Occupancy. The Life Safety level was used for both buildings on the pro

